	Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
	L1	 16	("20030011984" "20030015983" "20030063437" "20030230939" "5099181" "5598314" "6128905" "6182902" "6198245" "6236184" "6356435" "6400045" "6438984" "6474409" "6505680" "6561261").PN.	US-PGPUB; USPAT; USOCR	OR	OFF .	2007/09/22 17:48
	L2	- 9	((NAYSEN) near2 (ROBERTSON)).INV.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L3	+8156	((RICARDO) near2 (ESPINOZA-IBARRA)).INV.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L4	+50(40)	((SACHIN) near2 (CHHEDA)).INV.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L5	+107	((NAYSEN) near2 (ROBERTSON)).INV.	EPO; JPO; DERWENT	OR	OFF	2007/09/22 17:48
	L6	+2/2	((RICARDO) near2 (ESPINOZA-IBARRA)).INV.	EPO; JPO; DERWENT	OR	OFF	2007/09/22 17:48
	L7	+2417	((SACHIN) near2 (CHHEDA)).INV.	EPO; JPO; DERWENT	OR	OFF	2007/09/22 17:48
	L8	٩	−417/23.1.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L9	ے	4 17/23.01.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
345	L10	3128	computer near5 fan	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
+83	L11	501	(motor with fan\$2) and (redundant or redundancy or backup) and (control same monitor)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	Ľ12	-0	tacometer and (fan with ("1st motor" and "second motor")) and (control same position)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L13	-0	tacometer and (fan with ((1st or first or 2nd or second) and motor)) and (control same position)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L14	-0	facometer and (fan and ((1st or first or 2nd or second) and motor)) and (control same position)	US-PGPUB; USPAT; USOCR	OR .	OFF	2007/09/22 17:48
+34 +30	L15	705	tachometer and (fan and ((1st or first or 2nd or second) and motor)) and (control same position)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
+30	L16	636	L15 and method	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
	L17	2243850	method.clm.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48

L18	۔	-Ł16 and "method.clm"	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
L19	6	"method.clm" and L16	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
L20	JN 303	L16 and method.clm.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
L21	327	L11 and method.clm.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
L22	0-	((motor with fan\$2) near (1st or 2nd or first or second)) near5 ((redundant or redundancy or backup) near5 (power near5 source\$2)) and (control same monitor)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:48
L23	1	((motor with fan\$2) with (1st or 2nd or first or second)) same ((redundant or redundancy or backup) near5 (power near5 source\$2))	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L24	1	((motor with fan\$2) with (1st or 2nd or first or second)) same ((redundant or redundancy or backup or 2nd or 1st) with (power near5 source\$2))	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L25	73773	(motor and fan) and (1st or 2nd or first or second) and (power source\$2)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L26	-8-	"4434389.pn" :	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L27	9	"4434389a.pn"	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L28	_1	"4434389".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L29	1	"4618806".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L30	1	"5572403".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L31	*	"5258676".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L32	1	"4618806".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L33	2	"10037758".rlan. or ("10".src. and "037758".ap.)	US-PGPUB; USPAT; USOCR; DERWENT	OR -	OFF	2007/09/22 17:49

L34		("4278881" "4428719" "4550267" "4607180" "4618806" "5577924" "5982064" "6166469" "6194798" "RE37261").PN. OR ("6700266").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L35	_0_	ენ2093149.frgp.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	OFF	2007/09/22 17:49
L36	_0	gb2093149.frpn.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	OFF	2007/09/22 17:49
L37	-0 9	gb2093149.oref.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	OFF	2007/09/22 17:49
L38	-0	GB19810004664.fipc.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR .	OFF	2007/09/22 17:49
L39	59400	hugh barrie doyle	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR ·	OFF	2007/09/22 17:49
L40	-0	"ĥugh barrie doyle"	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	OFF	2007/09/22 17:49
L41	-8	GB2093149.oref.	US-PGPUB; USPAT; USOCR; EPO; DERWENT	OR	OFF	2007/09/22 17:49
L42		GB2093149.oref.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L43	٠	"GB.prco"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49

L44	658006	GB.prco.	US-PGPUB; USPAT;	OR	OFF	2007/09/22 17:49
	,		USOCR; EPO; JPO; DERWENT ; IBM_TDB			
L45	5997 + 384	L44 and hugh barrie	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L46	52	L45 and doyle	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L47	0	"GB002116305"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR ·	OFF	2007/09/22 17:49
L48	4130776	packaged air conditioning equipment.as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	.2007/09/22 17:49
L49	_10-	packaged air conditioning equipment.as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	AND	OFF	2007/09/22 17:49
L50	<i>J</i> €	"packaged air".as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	AND	OFF	2007/09/22 17:49
L51		1982-L1638E.NRAN.	DERWENT	OR	OFF	2007/09/22 17:49
L52	1	1982-L1638E.NRAN.	DERWENT	OR	OFF	2007/09/22 17:49
L53	_10	("4278881" "4428719" "4550267" "4607180" "4618806" "5577924" "5982064" "6166469" "6194798" "RE37261").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L54	10	("6700266").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L55	HY 86	417/16.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L56	8	("1601934" "3477637").PN. OR ("5938407"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

	/	LAST Scaren in				
L57	+ 41,806	417/423.1.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L58	2	09/796351.app.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L59	A3 14	("3644066" "5133617" "5407324" "5498130" "5839205" "6244818" "6375440").PN. OR ("6612817").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L60		L57 and replaceable near5 motor	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L61		L57 and replaceable same (motor or rotor or power source)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L62	3	257 and replaceable same (motor or rotor or power source or auxilary or backup)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L63	+ No 227	L57 and motor with (power source or auxilary or backup)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L64	429	417/374.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L65	9	("2003/0122438").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L66	2 17	("20050095138" "2936107" "3477637" "4352635" "5008561" "5436827" "5759016" "5938407" "6040668" "6400045" "6626653" "6819017").PN. OR ("6956344"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L67	24	("2073404" "2252762" "2397183" "2936107" "3650633" "4092088" "4108580").PN. OR ("4352635").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L68	26	("20030123767" "3737202" "3959677" "4203319" "4278881" "4428719" "4434389" "4550267" "4618806" "4738336" "5008561" "5258676" "5267842" "5315954" "5572403" "5577924" "6166469" "6208923" "6445099" "6548969").PN. OR ("6819017").URPN.	US-PGPUB; USPAT; USOCR	.OR	OFF	2007/09/22 17:49
L69	112	("2952787" "3903404" "4386651" "4756473" "4774631" "5136465" "5438226").PN. OR ("5572403").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L70		("4168160" "4278881" "4434389" "4544039" "4550617" "4618806" "4803885" "4865143" "5258676" "5572403" "6257065").PN. OR ("6826970").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L71	24	("20030123767" "3737202" "3959677" "4203319" "4278881" "4428719" "4434389" "4550267" "4618806" "4738336" "5008561" "5258676" "5267842" "5315954" "5572403" "5577924" "6166469" "6208923" "6445099" "6548969").PN. OR ("6819017").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

		LAST Search III	,			
L72	1/2/12	("2952787" "3903404" "4386651" "4756473" "4774631" "5136465" "5438226").PN. OR ("5572403").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L73	+Q 51	("4400654" "5200684" "5269660" "5572403" "5631852" "5687079" "5689159" "5790430" "5847524" "5929577" "5949646" "6023402" "6031717" "6037732" "6054823" "6101459" "6151023" "6160358" "6188973" "6191957" "6198176" "6216235" "6246969" "6260155" "6265841" "6268664" "6276900" "6298449" "6318965" "6321348" "6337630" "6338150" "6344985" "6348873" "6392372" "6398505" "6400113" "6481974" "6487463" "6545438" "6597972" "6611117" "RE35124").PN. OR ("6725132").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L74	129	("5099181" "5526289" "5534854" "5563486" "5568350" "5574667" "Re33167").PN. OR ("5790430").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L75	10 16	("4289997" "4702154" "4797600" "5672943" "5739648" "5949646" "6141213" "6318965" "6326747" "6398505" "6501648" "6725132" "6750562" "6814546" 6932696").PN. OR ("7135826").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L76	↓ \\ 39	("4502100" "4751872" "4756473" "4767262" "4899254" "5163870" "5193050" "5247427" "5285347" "5339214" "5398159" "5409419" "5438226" "5484012" "5490723" "5493474" "5505533" "5540548" "5562410" "5572403").PN. OR ("6042474").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L77	24	("20030123767" "3737202" "3959677" "4203319" "4278881" "4428719" "4434389" "4550267" "4618806" "4738336" "5008561" "5258676" "5267842" "5315954" "5572403" "5577924" "6166469" "6208923" "6445099" "6548969").PN. OR ("6819017").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L78	8	("2003/0178954").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L79	16 14	("3644066" "5133617" "5407324" "5498130" "5839205" "6244818" "6375440").PN. OR ("6612817").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L80	£1 10	("4278881" "4428719" "4550267" "4607180" "4618806" "5577924" "5982064" "&166469" "6194798" "RE37261").PN. OR ("6700266").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L81	+D-/23	("3529264" "4749968" "4896349" "4993064" "5147992" "5149416" "5246378" "5280254" "5348491" "5382173").PN. OR ("5577924").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L82	19806	917/423.1.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L83	10	L82 and ((switch or alternate or backup) near5 motor) and engage and fan	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

		/	-			
L84	118	L82 and ((switch or alternate or backup or multiple or 2nd or second) near5 motor\$2) and engage and fan	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L85	10	L82 and ("backup motor" or "2nd motor" or "second motor") near4 fan and switch	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L86	/2	L82 and ("backup motor" or "2nd motor" or "second motor") and fan and switch	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L87	5	282 and "switch motor" and fan	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L88	67	L82 and "fan motor"	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L89	1509	319/112. ccls.	US-PGPUB; USPAT; USOCR	OR	OFF .	2007/09/22 17:49
L90	124	L89 and fan	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L91	1 20	("2700343" "2976352" "3083893" "3175755" "4010716" "4571528" "4612468").PN. OR ("5258676").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L92	,38	("1365871" "1985022" "2121073" "2313413" "3038307" "3088414" "3127093" "3187189" "3270820" "3291381" "3574477" "4182118" "4336748" "4453816" "4563126" "5258676" "5546272" "5720661" "5820345" "5931640" "5944497" "5984631" "6386276" "6565334" "6612817" "6626653" "6652230" "6663342").PN. OR ("7059830").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L93	¥3 18	("3083893" "4164852" "5258676" "5572403" "6244818" "6343014" "6537019" ("6612817" "6626653" "6663342").PN. OR ("6827549").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L94	LZ 13	("6244818" "6547540").PN. OR ("6663342"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L95		("3644066" "3868992" "4123197" "5572403" "5839205" "6406257" "6612817" "6652230" "6663342").PN. OR ("6904960"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L96	20	("20020018336" "20020060900" "4080096" "6017185" "6244818" "6386276" "6388880" "6407919").PN. OR ("6547540").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L97	ft 19	("2709035" "3274410" "3449605" "4167376" "6109890" "6129528" "6283726").PN. OR ("6386276").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L98	87690	(backup or second or alternate) and fan and (motor or motor near5 redundant)	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

	,			r	1	1
L99	11168	L98 and switch near5 motor	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L100	3676	L99 and motor near5 ((second or alternate or 2nd) "power source")	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L101	32	L100 and fan near5 computer	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L102	3	US-6021042-\$.DID. OR US-6134108-\$.DID. OR US-6648065-\$.DID.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L103	23 29	("4756473" "4817865" "5019880" "5361188" "5409352" "5640046" "5661638").PN. OR ("6134108").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L104	16-228	("3843910" "4214706" "4261519" "4417295" "4463897" "4674004" "4851965" "5321581" "5559673" "5566377" "5640046" "5751549" "6021042" "6134108" "6141213" "6280318").PN. OR ("6525936"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L105	49 49	("20020152932" "3609991" "3815377" "4552303" "4593360" "4616777" "4730772" "4817865" "4997030" "5076346" "5207613" "5220804" "5253484" "5261243" "5315793" "5315837" "5474120" "5478584" "5503032" "5565180" "5576218" "5718117" "5718628" "5740018" "5806762" "5903433" "5907473" "5943211" "6026896" "6108206" "6129285" "6134108" "6159091" "6205796" "6205799" "6415619" "6427466" "6490877" "6525935" "6525936" "6574104" "6578828" "6616524" "6628520" "6644058").PN. OR ("6904968").URPN.	US-PGPUB; USPAT; USOCR	OR ·	OFF	2007/09/22 17:49

						•
L106	A	(US-20020152932-\$).did. or (US-7000412-\$ or US-6644058-\$ or US-6628520-\$ or US-6616524-\$ or US-6578828-\$ or US-6574104-\$ or US-6525936-\$ or US-6525935-\$ or US-6427466-\$ or US-6415619-\$ or US-6205799-\$ or US-6205796-\$ or US-6159091-\$ or US-6134108-\$ or US-6159091-\$ or US-6108206-\$ or US-6129285-\$ or US-5108206-\$ or US-5907473-\$ or US-5903433-\$ or US-5907473-\$ or US-5740018-\$ or US-5718628-\$ or US-5718117-\$ or US-5718628-\$ or US-5785117-\$ or US-5576218-\$).did. or (US-5565180-\$ or US-5474120-\$ or US-5478584-\$ or US-52315793-\$ or US-52076346-\$ or US-5207613-\$ or US-52076346-\$ or US-4997030-\$ or US-4817865-\$ or US-4730772-\$ or US-4817865-\$ or US-4730772-\$ or US-4817865-\$ or US-4593360-\$ or US-4552303-\$ or US-3815377-\$ or US-3609991-\$).did. or (US-3609991-\$).did.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L107	JH 29	("5467609" "5477417" "5570740" "5767690" "6123266" "6134108" "6205796" "6208510" "6279337").PN. OR ("6628520"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L108	J 29	("4756473" "4817865" "5019880" "5361188" "5409352" "5640046" "5661638").PN. OR ("6134108").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L109	کلار ا	("2830521" "3426984" "4351501" "4432514" "5253484" "5474120" "5545084" "5695396").PN. OR ("6159091").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L110	39	("1953727" "3198433" "3570472" "3635210" "3689037" "3770254" "3774588" "3776215" "3802161" "3855371" "3900301" "3923482" "3990427" "4042016" "4078480" "4272014" "4290274" "4365619" "4367787" "4494596" "4508551" "4747980" "4879075" "4906417" "4913856" "4967726" "4967728" "5082173" "5497628" "5525268" "5620503" "5699983" "5740790" "5762661").PN. OR ("6129285").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L111	F/6 52	("3903404" "4337499" "4774631" 4874127" "5000079").PN. OR ("5718628"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L112	¥ X 34	("5467609" "5718628" "5956228" "6142866" "6374627" "6412292").PN. OR ("6574104").URPN.	US-PGPUB; USPAT; USOCR	OR .	OFF	2007/09/22 17:49
L113	28	("3030024" "3053454" "3801467" "4706736" "4865986" "4868122" "4963499" "4981801" "5028541" "5038852" "5123477" "5133936" "5176203" "5187084" "5281516" "5455175").PN. OR ("5576218"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

	_					
L114	+261	("2768879" "3192968" "3549330" "3926737" "4271123" "4298571" "4424559" "4483823" "4499052" "4543238").PN. OR ("4981801").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L115	32	("3650306" "4396579" "4493815" "4526690" "4908320" "4971514" "4981801" "5108704" "5167922" "5219528" "5288464" "5324483" "5332549" "5416329" "5455008" "5456882" "5460783" "5470744" "5518686" "5620894" "5645800" "5686047" "5738827").PN. OR ("6323035"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L116	J82	("3297250" "3826963" "4530395" "4635445" "4646964" "4716957" "4754919" "4830095" "4890666").PN. OR ("5076346"). \URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L117	A 44	("2038578" "3844475" "4009825" "4126269" "4182484" "4244517" "4406397" "4422571" "4523715" "4533080" "4607789" "4702154" "4722669").PN. OR ("4817865").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L118	43	("4756473" "4817865" "5121291" "5249741" "5287244" "5436827" "5469320" "5484012" "5513361" "5574667" "5631800" "5687079" "5726874" "5727928" "5777897" "5790430" "5825642" "5848282" "5920264" "5926367" "5926386" "5929581" "5963887" "5974557" "6005762" "6006168" "6014611" "6023402" "6058012" "6101459" "6134667" "6158012" "6216235" "6336592" "6337630").PN. OR ("6654894").URPN.	US-PGPÜB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L119	IX 1	("2005/0163615").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L120	10° /3°	US-4539487-\$.DID. OR US-6034444-\$.DID. OR US-6735704-\$.DID.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L121	10	(*4278881" "4428719" "4550267" "4607180" "4618806" "5577924" "5982064" "6166469" "6194798" "RE37261").PN. OR ("6700266").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L122	x 92	417/16.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L123	12199	417/5.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49

Page 10

		LAST Scarcit III	.5.0. ,			
L124	¥ 21 85	417/6.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L125	X	("replaceable motor" or "motor replacement") and (motor near5 switching and mechanism) and fan	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L126	2	("replaceable motor" or "motor replacement") and (motor and switching and mechanism) and fan	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L127	1423	(motor and switching and mechanism and replace) and fan	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L128	5 337_	(motor-and ((switching or switch or change or select or alternate) with motor\$2) and mechanism) and (replace\$5 or backup) and fan	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L129	HY 87	L128 and "control unit" and tachometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR .	OFF	2007/09/22 17:49
L130-	5508	(motor and ((hybrid or switching or switch or change or select or alternate) with motor\$2) and mechanism) and (replace\$5 or backup) and fan	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT ; IBM_TDB	OR	OFF	2007/09/22 17:49
L131	18	("3421389" "3435616" "3757524" "4098083" "4179888" "4711090" "4799851" "5199525" "5347812" "5535845").PN. OR ("5687568").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

			•			
L132	\$2	("2500627" "2585348" "2616259" "3641879" "3664129" "3768263" "3981150" "4005636" "4043419" "4075840" "4130990" "4144946" "4174018" "4179888" "4189919" "4206689" "4223646" "4275688" "4343151" "4410058" "4414809" "4420934" "4446697" "4463557" "4470259" "4488569" "4556078" "4625751" "4664210" "4738330" "4798050" "4941437" "4966066" "5293952" "5398505" "5471908" "5487403" "5587568" "5727389" "5836347" "5881630" "6021641" "6158216" "6209566").PN. OR ("6629411"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L133	20	("3421389" "3435616" "3757524" "4098083" "4179888" "4711090" "4799851" 	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L134	18	("3421389" "3435616" "3757524" "4098083" "4179888" "4711090" "4799851" "5199525" "5347812" "5535845").PN. OR ("5687568").URPN.	US-PGPUB; USPAT; USOCR	OR ·	OFF	2007/09/22 17:49
L135	13/	("2616259").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L136	A 3 17	("20050095138" "2936107" "3477637" "4352635" "5008561" "5436827" "5759016" "5938407" "6040668" "6400045" "6626653" "6819017").PN. OR ("6956344"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L137	18	("1601934" "3477637").PN. OR ("5938407"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L138	3	("3477637").URPN.	USPAT	OR	OFF	2007/09/22 17:49
L139	ور _	("2936107" "4398872" "4697991" "4756473" "5035585").PN. OR ("5759016"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

9/22/2007 5:56:09 PM H:\3746 Cases\App 10-699430 Scalable Modular Fan\10699430 Search v1.wsp Page 12

L140	4 149	("3345551" "3940671" "4057847" "4126269" "4296363" "4465958" "4672535" "4707803" "4751440" "4769764"	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
		"4992709" "5006961" "5051720" "5157663" "5210855" "5253348" "5266838"				
		"5287244" "5307354" "5351276" "5386567" "5404494" "5432946" "5440748"				
		"5473499" "5483419" "5484012" "5487148"			'	
'						
		"5568619" "5572403" "5577155"				
		"5577205" "5579491" "5581712" "5581714" "5588144" "5598407" "5606672"				
		"5608876" "5615207" "5621159" "5622221"				
				;		
		"5655081" "5655148" "5659682" "5664119" "5666538" "5671371" "5675723"				
		"5680288" "5684671" "5687079"				
		"5689637" "5696899" "5696970" "5724529" "5726506" "5737708" "5740378"				
		"5742833" "5745041" "5747889" "5748426"		:		
		"5752164" "5754797" "5759016" "5761033" "5761045" "5761462" "5764968"				
		"5765008" "5765198" "5768541"				
		"5768542" "5774741" "5778197" "5781703" "5781767" "5781798" "5784576"	0			,
		"5787459" "5787971" "5790775" "5790831" "5793987" "5794035" "5796185"				
		"5796580" "5796981" "5798828" "5799036"				
,						
		"5812750" "5812757" "5812858"				
	`/	"5815117" "5815652" "5822547").PN. OR ("5835738" "5841991" "5852720" "5857074").PN. OR ("6247898").URPN.				•
L141	L 29	("4401351" "4751872" "4847600" "5121291" "5287009" "5287244" "5436827" "5438226" "5444436").PN. OR ("5745041"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L142	18	("20020004913" "4203319" "4278881" "4428719" "4434389" "4550267" "4618806" "4738336" "5008561" "5258676" "5572403" "5577924" "5745041" "5963887" "6166469" "6646851").PN. OR ("6791209").	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
		URPN.				
L143	₩ ²⁰	("2700343" "2976352" "3083893" "3175755" "4010716" "4571528" "4612468").PN. OR ("5258676").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L144 _.	1	(("DONALD C") near2 (GARRETT)).INV.	EPO; JPO; DERWENT	OR	OFF	2007/09/22 17:49
L145	X	(("DONALD C") near2 (GARRETT)).INV.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49

			ı 			
L146	18	("0912198" "1818643" "2185338" "2902886" "2905011" "3299685" "3612729" "4068984" "4408891").PN. OR ("5035585"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L147	21	("2073404" "2252762" "2397183" "2936107" "3650633" "4092088" "4108580").PN. OR ("4352635").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L148		"10699430".app.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L149		10/699430.app.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L150	13	US-2936107-\$.DID. OR US-3477637-\$.DID. OR US-4352635-\$.DID. OR US-6400045-\$.DID. OR US-5008561-\$.DID. OR US-5759016-\$.DID. OR US-6626653-\$.DID. OR US-5938407-\$.DID. OR US-6819017-\$.DID. OR US-6040668-\$.DID. OR US-5436827-\$.DID.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L151	2	10/038160.app.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L152	1	10/038160.app.	USPAT	OR	OFF	2007/09/22 17:49
L153	1	10/699430.app.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/22 17:49
L154	0	10/699430.app.	USPAT	OR	OFF	2007/09/22 17:49



Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	309539	(replac\$5 motor computer fan).clm.	US-PGPUB	OR	OFF	2007/09/22 18:43
L2	1	(replac\$5 motor computer fan).clm.	US-PGPUB	SAME	OFF	2007/09/22 18:43
L3	39	(motor fan computer).clm.	US-PGPUB	SAME	OFF	2007/09/22 18:45
L4	0	(motor fan fail).clm.	US-PGPUB	SAME	OFF	2007/09/22 18:45
L5	2	(computer fan fail).clm.	US-PGPUB	SAME	OFF	2007/09/22 18:46
L6	5	(computer fan tachometer).clm.	US-PGPUB	SAME	OFF	2007/09/22 18:46